

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No 128048

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080184-0

RECEIVED FROM

DATE REC'D 1-14-57
P. O. NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W. O. NO. S. O. NO.
	322	000000	20017	0	0	00	00	00		
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY		REMARKS	
8	738268 PAUER SWITCH ACTUATOR						ACCEPTED	REJECTED		
	SHIP MEMO 85838									

RECEIVED BY: INSPECTED BY: DATE 1/14/57 REJECTS RETURNED ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA 8, CALIF.

No 128049

RECEIVED FROM

DATE REC'D 1-14-57
P. O. NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W. O. NO. S. O. NO.
	322	000000	20005	0	0	00	00	00		
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY		REMARKS	
2	735304 CHAM SHAFT ASSEMBLY						ACCEPTED	REJECTED		
	SHIP MEMO 85838									

RECEIVED BY: INSPECTED BY: DATE 1/14/57 REJECTS RETURNED ON SHIP MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080184-0